

Załącznik nr 2 do ogłoszenia

ZBĘDNE SKŁADNIKI MAJĄTKOWE – OPIS STANU TECHNICZNEGO

Lp.	Model	Numer inwentarzowy	Parametry/ Stan techniczny
1	NTT System Q57M-S2H	SN-09-8089/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
2	NTT System Q57M-S2H	SN-09-8083/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
3	NTT System Q57M-S2H	SN-09-8096/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
4	NTT System Q57M-S2H	SN-09-8119/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
5	NTT System Q57M-S2H	SN-09-8102/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
6	NTT System Q57M-S2H	SN-09-8101/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
7	NTT System Q57M-S2H	SN-09-8131/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
8	NTT System Q57M-S2H	SN-09-8126/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
9	NTT System Q57M-S2H	SN-09-8085/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
10	NTT System Q57M-S2H	SN-09-8081/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,

11	NTT System Q57M-S2H	SN-09-8099/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
12	NTT System Q57M-S2H	SN-09-8100/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
13	NTT System Q57M-S2H	SN-09-8121/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
14	NTT System Q57M-S2H	SN-09-8129/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
15	NTT System Q57M-S2H	SN-09-8074/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
16	NTT System Q57M-S2H	SN-09-8097/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
17	NTT System Q57M-S2H	SN-09-8133/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
18	NTT System Q57M-S2H	SN-09-8077/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
19	NTT System Q57M-S2H	SN-09-8098/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
20	NTT System Q57M-S2H	SN-09-8122/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
21	NTT System Q57M-S2H	SN-09-8139/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", uszkodzona obudowa

22	NTT System Q57M-S2H	SN-09-8075/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
23	NTT System Q57M-S2H	SN-09-8128/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
24	NTT System Q57M-S2H	SN-09-8130/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
25	NTT System Q57M-S2H	SN-09-8146/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
26	NTT System Q57M-S2H	SN-09-8132/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
27	NTT System Q57M-S2H	SN-09-8145/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
28	NTT System Q57M-S2H	SN-09-8134/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
29	NTT System Q57M-S2H	SN-09-8073/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
30	NTT System Q57M-S2H	SN-09-8127/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
31	NTT System Q57M-S2H	SN-09-8144/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,
32	NTT System Q57M-S2H	SN-09-8147/4/10	Intel(R) Pentium(R) CPU G6950 @ 2.80GHz, Intel(R) HD Graphics (Pentium), Intel(R) 82578DM Gigabit Network Connection, Brak pamięci RAM, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2010 roku,

33	HP Compaq dc7800 Small Form Factor	S-09-0395/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
34	HP Compaq dc7800 Small Form Factor	S-09-0378/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
35	HP Compaq dc7800 Small Form Factor	S-09-0377/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
36	HP Compaq dc7800 Small Form Factor	S-09-0400/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
37	HP Compaq dc7800 Small Form Factor	S-09-0384/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
38	HP Compaq dc7800 Small Form Factor	S-09-0383/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
39	HP Compaq dc7800 Small Form Factor	S-09-0386/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
40	HP Compaq dc7800 Small Form Factor	S-09-0389/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
41	HP Compaq dc7800 Small Form Factor	S-09-0397/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
42	HP Compaq dc7800 Small Form Factor	S-09-0382/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,
43	HP Compaq dc7800 Small Form Factor	S-09-0388/4/07	Intel(R) Core(TM)2 Duo CPU E6550 @ 2.33GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2 GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2007 roku,

44	HP Compaq dc7800p Small Form Factor	S-09-0435/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
45	HP Compaq dc7800p Small Form Factor	S-09-0464/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
46	HP Compaq dc7800p Small Form Factor	S-09-0481/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
47	HP Compaq dc7800p Small Form Factor	S-09-0471/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
48	HP Compaq dc7800p Small Form Factor	S-09-0432/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
49	HP Compaq dc7800p Small Form Factor	S-09-0483/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
50	HP Compaq dc7800p Small Form Factor	S-09-0467/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
51	HP Compaq dc7800p Small Form Factor	S-09-0452/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
52	HP Compaq dc7800p Small Form Factor	S-09-0482/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
53	HP Compaq dc7800p Small Form Factor	S-09-0457/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
54	HP Compaq dc7800p Small Form Factor	S-09-0442/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,

55	HP Compaq dc7800p Small Form Factor	S-09-0433/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
56	HP Compaq dc7800p Small Form Factor	S-09-0437/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
57	HP Compaq dc7800p Small Form Factor	S-09-0475/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
58	HP Compaq dc7800p Small Form Factor	S-09-0486/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
59	HP Compaq dc7800p Small Form Factor	S-09-0470/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
60	HP Compaq dc7800p Small Form Factor	S-09-0474/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
61	HP Compaq dc7800p Small Form Factor	S-09-0460/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
62	HP Compaq dc7800p Small Form Factor	S-09-0459/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku,
63	HP Compaq dc7800p Small Form Factor	S-09-0469/4/08	Intel(R) Core(TM)2 Duo CPU E8300 @ 2.83GHz, TSSTcorp DVD-ROM TS-H353B ATA Device, Intel(R) GMA 3100, SoundMAX Integrated Digital HD Audio, Intel(R) 82566DM-2 Gigabit Network Connection, RAM 2GB, Brak HDD, monitor LCD 19", sprawny, zakupiony w 2008 roku, brak pamięci RAM
64	Zestaw serwerowy	S-09-0247/4/05	Serwer Fujitsu-Siemens PRIMERGY TX200 S2, 4 x Intel Xeon 2.0 GHz, 2GB RAM, wymontowane dyski twarde zakupiony w 2005 roku, sprawny.
65	System telewizji kablowej w serwerowni OT 203/2003	S-09-0204/6/03	Rejestrator Mitsubishi DX-TL800 System uruchomiony w 2003 roku, wraz z systemem zabezpieczeń CCTV zakupionym w 2005 roku. Wymontowane nośniki danych z rejestratora.

66	Macierz HP Disk Array XP12000	S-09-0348/4/06	Macierz dyskowa HP XP12000. Cache: 20GB, Shared Memory: 4GB, wymontowane dyski twarde.
67	Macierz XP 24000	S-09-0422/4/07	Macierz dyskowa HP XP24000. Cache: 24GB, Shared Memory: 6GB, wymontowane dyski twarde.
68	Ruter Juniper J 4300	S-09-0371/4/06	Sprawny
69	Ruter Juniper J 4300	S-09-0370/4/06	Sprawny
70	Biblioteka taśmowa HPMSL6030	S-09-0347/4/06	Biblioteka taśmowa, dwa napędy Ultrium LTO-3, 30 slotów na taśmy magnetyczne LTO Uszkodzony robot sterujący ładowaniem taśm.

